

Changelog Smart Soundbox 3

29.10.2019

German:

Alte Firmware Revision: MCU v0.54; STS 1.12, WIF 10505, DSP 056

Neue Firmware Revision: MCU v0.78; STS 1.17, WIF 12028, DSP 060

Verbesserung der Funktionen:

- Allgemeine Stabilitätsverbesserungen
- Update Google Cast auf Version 1.36.145856
- Ab sofort werden STS Verbindungen für zukünftige Updates gespeichert
- Menüpunkt LAN zum Ändern der Sprache SYS Menü eingeführt (Englisch und Deutsch)
- Menüpunkt TXP zur Anpassung der Funkleistung im WIS Menü eingefügt
- Menüpunkt CHN zur Anpassung des Funkkanals im WIS Menü eingefügt
- 2,4 GHz Bereich für die Funkverbindung aktiviert
- Menüpunkt UIS zum Aktivieren der Laufschrift

English:

Old Firmware Revision: MCU v0.54; STS 1.12, WIF 10505, DSP 056

New Firmware Revision: MCU v0.78; STS 1.17, WIF 12028, DSP 060

Improvement of functions:

- General stability improvements
- Updating Google Cast to version 1.36.145856
- From now on, STS connections will be saved for future updates
- Menu item LAN in the SYS menu for changing the language (English and german)
- Menu item TXP in WIS menu for adaption of the wireless performance
- Menu item CHN in WIS menu for adaption of the wireless channel
- 2,4 GHz range for radio connection activated
- Menu item UIS for activating the ticker